

Members were also able to inspect an additional Sociable engine unit, which has recently been purchased by the Museum authorities. Our President Harold Scott, made a substantial donation towards the cost of purchasing the latter.

The meeting concluded at about 4.00 p.m. when our Chairman Colin Pinder proposed a vote of thanks to Griff for a most interesting and enlightening afternoon.

**Martin Hodkin**

## Stop press — another new Section

### South/West Wales Section

By the time you read these notes the first meeting of the South/West Wales Section will have been held. Scott owners in the area have been contacted by letter and, judging by the response, we should have a good turn out. It is the intention to hold monthly meetings at the "Ceasers Arms", Creigiau, near Cardiff. Dates to be arranged at the first meeting.

**Dick Scott,**

119 Glenbrook Drive,

Barry,

South Glamorgan CF6 7FB.

## PETERBOROUGH RALLY 1985

Following last year's rally, Frank Serjeant has very kindly invited the S.O.C. to hold another rally at his farm this year. It will take place on August 31st and there are facilities for overnight camping. Further details will appear in the August issue.

## SILK SPARES

**P. Barrenger**

With regard to the note from John Barney in the February issue of *Yowl*, here is a list of names and addresses for Silk spares.

Item	Make	Part No., etc.
Petrol tap	Suzuki	44300-05112
Rear brake shoes	EBC	Cast wheel only Y514
Rear brake shoes	Yamaha	350-250 RD
Front pads	Mintex LDB 19 or GKN	Master parts MDP 2002
Lumination,	Autocar	MCK 901
40 Ripple Rd.,	Lumination Div.,	(state which side wire
Barking,	Chantry Rd Indust Est,	enters crankcase)
Essex.	Kempston, Bedford	
Fork gaiters	Triumph, BSA, std type	(Triumph dealer)
Chain gaiters	MZ ES 250	(MZ dealer)
Zenor diode	Lucas or Triumph	Lucas Y49589a 7724
Master cylinder	Automotive Products PLC,	CP2215-20
repair kit	Racing Div,	(single disc $\frac{1}{2}$ bore)
	Tachbrook Rd,	CP2410-20
	Leamington Spa.	(Twin disc .700 bore)
Battery	12N7 4B — 12v 7ah	(Honda dealer)
Rear damper	Girling	70056069D GH28
Rev. counter	44 Somers Rd, Rugby,	Veglia GCA
	Warwicks.	(Note: loss of needle and
	0788 62928	rev counter not working,
		possibly due to pod being
		too rigid)

*(All these foreign names and strange numbers! I hope I have reproduced them accurately. Ed.)*