

Silk Proprietary Parts

<u>Item</u>	<u>Make</u>	<u>Pt No etc</u>	<u>Source/Yr</u>
<u>Brakes</u>			
Front Brake Pads	Ferodo	FDB 342	Y03
Front Brake Pads	Lockheed	LMP 123	Y03
Front Brake Pads	Dunlop	DP500	Y03
Front Brake Pads	Brembo	BB LK01	Y03
Front Brake Pads	EBC	FA16	Y03
Front Brake Pads	Mintex	LBD19	
CW93, Y85			
Front Brake Pads	GKN	MDP2002	CW93, Y85
<u>Master Cylinder Repair Kits</u>			
Single Disc(0.625" bore)	AP Racing*	CP 2215-20RK	CW93, Y03
Double Disc(0.700" bore)		CP2410-1RK	CW93, Y03
Spondon Caliper Seal	Norton Commando		CW93
Rear Brake Shoes(cast)	EBC	Y514	CW93, Y85
Rear Brake Shoes(spoked)	Yamaha	RD 250/350	Y85
Spondon Fork Seal	(2 per leg, invert top)	38 x 50 x 7mm	CW93
Rear SuspensionUnits	Girling	70056069D GH28	Y85
Fork Gaiters	BSA	Standard Type	CW93, Y85
Chain Gaiters	MZ	ES250	CW93, Y85
Tank Mounts	Rover	GEX 7251	Y03
Mk 2 Petrol Tap	Suzuki	44300-05112	CW93, Y85
Bar Switch Gear	Suzuki	GS750 EC	CW93
Clutch Lever	Suzuki	GS750	CW93
Rev Counter	Veglia	GCA	Y85
Rev Counter	Citroen	2CV	CW93
Radiator Mounts	Rover	GEX 7251	Y03
Radiator Hoses	Gates	7027ES	CW?93
Radiator Hoses	Quinton Hazell	QH556	Y03
Crank Seals		30 x 40 x 7mm(2 off)	CW93
Carburettor	Amal	38mm MK2 2030/302	CW93
	Needle	2DI	
	Slide	2½	
	Pilot Jet	25?	
	Main Jet	480	
Ignition System	Lumenition*	Mk12 (- 75)Finned box	CW93
		Mk16 (76-80) Alloy box, red/black	
		Mk17 (81 on) Alloy box, white exit	
Ignition system(replace)	Boyer (AO Serv)*	Norton Jubilee twin	Y03
	Boyer	Silk specific unit now available	

Sources

CW93 - Clive Worrall price list 1993
Y85 - Yowl article 1985 - P Barrenger
Y03 - Yowl article 2003 - D Cameron

*Addresses

(checked July 2010)

AP Racing: Wheler Road, Coventry, CV3 4LB
Telephone 01203 639595 Web: www.apracing.com

Lumenition: Autocar Equip.Ltd., 49-51 Tiverton Street, London, SE1 6NZ
Telephone 020 7403 4334 Web: www.autocar-electrical.com

AO Services 35 Griston Road, Thetford, IP25 6DN
Telephone 01953 884681 Web www.aoservices.co.uk